

IPP OPERATIONS

February 29, 2008

Code	Name	Source	Current Status	IPV2 Status
0x0002	Print-Job	RFC 2566	required	
0x0003	Print-URI	RFC 2566	optional	
0x0004	Validate-Job	RFC 2566	required	
0x0005	Create-Job	RFC 2566	optional	
0x0006	Send-Document	RFC 2566	optional	
0x0007	Send-URI	RFC 2566	optional	
0x0008	Cancel-Job	RFC 2566	required	
0x0009	Get-Job-Attributes	RFC 2566	required	
0x000A	Get-Jobs	RFC 2566	required	
0x000B	Get-Printer-Attributes	RFC 2566	required	
0x000C	Hold-Job	RFC 2911	optional	
0x000D	Release-Job	RFC 2911	optional	
0x000E	Restart-Job	RFC 2911	optional	
0x0010	Pause-Printer	RFC 2911	optional	
0x0011	Resume-Printer	RFC 2911	optional	
0x0012	Purge-Jobs	RFC 2911	optional	
0x0013	Set-Printer-Attributes	RFC 3380	optional	
0x0014	Set-Job-Attributes	RFC 3380	optional	
0x0015	Get-Printer-Supported-Values	RFC 3380	optional	
0x0016	Create-Printer-Subscriptions	RFC 3995	required	
0x0017	Create-Job-Subscriptions	RFC 3995	required	
0x0018	Get-Subscription-Attributes	RFC 3995	required	
0x0019	Get-Subscriptions	RFC 3995	required	
0x001A	Renew-Subscription	RFC 3995	required	
0x001B	Cancel-Subscription	RFC 3995	required	
0x001C	Get-Notifications	RFC 3996	required	
0x001D	Send-Notifications	INDP (draft)	N/A	
0x0022	Enable-Printer	RFC 3998	optional	
0x0023	Disable-Printer	RFC 3998	optional	
0x0024	Pause-Printer-After-Current-Job	RFC 3998	optional	
0x0025	Hold-New-Jobs	RFC 3998	optional	
0x0026	Release-Held-New-Jobs	RFC 3998	optional	
0x0027	Deactivate-Printer	RFC 3998	optional	
0x0028	Activate-Printer	RFC 3998	optional	
0x0029	Restart-Printer	RFC 3998	optional	
0x002A	Shutdown-Printer	RFC 3998	optional	
0x002B	Startup-Printer	RFC 3998	optional	
0x002C	Reprocess-Job	RFC 3998	optional	
0x002D	Cancel-Current-Job	RFC 3998	optional	
0x002E	Suspend-Current-Job	RFC 3998	optional	
0x002F	Resume-Job	RFC 3998	optional	
0x0030	Promote-Job	RFC 3998	optional	
0x0031	Schedule-Job-After	RFC 3998	optional	
0x0033	Cancel-Document	PWG 5100.5	required	
0x0034	Get-Document-Attributes	PWG 5100.5	required	
0x0035	Get-Documents	PWG 5100.5	required	
0x0036	Delete-Document	PWG 5100.5	optional	
0x0037	Set-Document-Attributes	PWG 5100.5	optional	

NOTE: Many optional operations must be implemented as a pair (e.g. Pause-Printer and Resume-Printer).